

Stream restoration

Native grass establishment poor in 2003. Clay may have been too compacted.



Photo by Mike Ryon

Stream restoration

Sparse grass development in 2004



Photos by Mike Ryon

Stream restoration

To improve restoration, top soil added next to stream, invasive plants treated, and more grass planted

Summer 2004



Photo by Mike Ryon

Stream restoration

Excellent grass development in 2005, addition of soil and replanting successful



September 2005



Photos by Mike Ryon