

Power line right of way

Poor establishment of native grass in 2003. Cover crop may have been too thick.



Photo by Mike Ryon

Power line right of way

Mixed success in 2004. Some wildflowers and sparse native grass established, but also extensive *Lespedeza*. Primary benefit was to prevent more fescue planting.



Photos by Mike Ryon

Power line right of way

Native grasses becoming more prominent
and additional wildflowers present



September 2005



Photos by Mike Ryon